



Selection Guide

Cryo-Gloves®

STYLE	MODEL				
	SIZE (US / EN)	SMALL / 8	MEDIUM / 9	LARGE / 10	X-LARGE / 11
Wrist	11 1/4" - 12 1/2" (290-320mm)	WRS	WRM	WRL	WRXL
Mid-Arm	13 1/2" - 15 1/4" (345-390mm)	MAS	MAM	MAL	MAXL
Elbow	17 1/4" - 19 1/4" (440-485mm)	EBS	EBM	EBL	EBXL
Shoulder	24 3/4" - 27" (625-685mm)	SHS	SHM	SHL	SHXL

Cryo-Apron®

STYLE	MODEL				
	SIZE (US / EN)	36" / 91.4cm	42" / 106.7cm	48" / 121.9cm	54" / 137.2cm
Apron		CA36	CA42	CA48	CA54

WATERPROOF Cryo-Gloves®

STYLE	MODEL				
	SIZE (US / EN)	SMALL / 8	MEDIUM / 9	LARGE / 10	X-LARGE / 11
Wrist	11 1/4" - 12 1/2" (290-320mm)	WRSWP	WRMWP	WRLWP	WRXLWP
Mid-Arm	13 1/2" - 15 1/4" (345-390mm)	MASWP	MAMWP	MALWP	MAXLWP
Elbow	17 1/4" - 19 1/4" (440-485mm)	EBSWP	EBMWP	EBLWP	EBXLWP
Shoulder	24 3/4" - 27" (625-685mm)	SHSWP	SHMWP	SHLWP	SHXLWP

CRYO-INDUSTRIAL® GLOVES

STYLE	MODEL			
	SIZE (US / EN)	MEDIUM / 9	LARGE / 10	X-LARGE / 11
Wrist	11 1/2" - 12 3/4" (295-325mm)	CIWMWP	CIWLWP	CIWXWP
Mid-Arm	13 3/4" - 15 1/4" (350-390mm)	CIMMWP	CIMLWP	CIMXWP
Gauntlet	17 1/4" - 18 1/2" (440-470mm)	CIGMWP	CIGLWP	CIGXWP

CRYO-INDUSTRIAL® APRON

STYLE	MODEL
	SIZE (US / EN)
Apron	CI-A42

Selection and Usage

- Proper fit contributes to product performance—a tight fit leads to thermal loss.
- Select the appropriate glove length and apron length for the specific application.
- Select **WATERPROOF Cryo-Gloves®** when working with cryogenic liquids—glove fit should be loose enough to allow for quick removal if necessary.
- Select **CRYO-INDUSTRIAL® GLOVES** when gloves are used in contact with abrasive surfaces.
- Store gloves and aprons in a clean dry space.
- Periodically inspect the condition of your gloves and aprons—replace garments that show excessive wear.



LabTeam Scandinavia AB
042-3009130
info@labteamet.com
order@labteamet.com
www.labteamet.com

PO Box 199, Mount Desert, ME 04660 USA

800-680-2796 (USA) 207 667 4747 (FAX)
+1 207-667-9696 (INTERNATIONAL)

www.cryogloves.com info@tempshield.com



SAFETY FIRST

**WEAR PROTECTIVE APPAREL
WHEN RISK IS PRESENT**

**KEEP GLOVES AND APRONS
READILY ACCESSIBLE**

Anyone handling cryogenic liquids should be familiar with the hazards presented by such materials and trained in how to handle them safely.

Emergency procedures should be established and rehearsed, proper training in the operation of all equipment provided and knowledge and appreciation of hazardous properties of the materials instilled.

Cryogenic liquids should never be handled without wearing proper protective apparel.

Recommended protective apparel for handling cryogenic liquids generally includes the following:

- Protective face shield or goggles
- Loose fitting gloves
- Protective apron without pockets
- Pants without cuffs
- Shoes without laces, or
- Spats covering shoes and area unprotected by apron

For more detailed information on safety precautions in specific settings please contact us at 800-680-2796.



CAUTION Not for immersion in liquid nitrogen.